Twinco Flying Club ground check procedures

General

- -Tiedown Alpha
- -FlightLevel Aviation fuel phone # 845-849-3770
- -Dog house combination:
- -Pilot lounge door combination:

Big Dog House

- -Extra oil and funnel be careful to not overfill engine crankcase
- -Clean windshield towels
- -Box for dirty towels
- -Isopropyl alcohol and spray tank used for frost/ice removal from wings DO NOT use on WINDSHIELD
- -Foot pump: tire air pressures listed in onboard flight logbook
- -Pre-heater should be used when overnight temps drop below 32 deg. Heat times stated in flight logbook.
- -Bug removal after every flight in warm weather; spray bottle and water in dog house.
- -Snow brush and shovels

Plane Exterior

- -Tie down straps with additional knot for safety
- -Interior gust lock must be installed first before exterior gust lock
- -Cowl plugs installed and rope routed OVER PROP
- -Don't forget pitot cover
- -Sun shades positioned during summer months
- -Tire chock positioned properly
- -REMOVE BUGS from plane surfaces using spray bottle of water in dog house
- -If battery tender is in use, plug it in after flight and check charging indicator

Plane Interior

- -Extra tie down ropes and chocks to go
- -Extra quart of oil
- -First aid kit
- -Tow handle Use to push plane back into tie down.
- -Install inside yoke gust lock before installing gust lock on tail
- -Be sure to use "Up elevator device" in seat back pocket when pushing plane back on soft surfaces
- -Glove box: contains flash light, POH and radio manuals for 737QC
- -fuel sump tool in seat back pocket
- -Flight instructor radio push to talk velcro switch in seat back pocket
- -Aircraft documents in pilot side pouch
- -Pilot's side seat is fitted with position safety latch
- -Both planes are equipped with an alternate vacuum source system for gyro instruments
- -Be sure to follow intercom squelch adjustment procedures Adjust volume before squelch
- -Be sure to leave the plane in NEAT and CLEAN condition with seat belts stowed
- -Leave BEACON SWITCH ON
- -PDF manuals for the following avionics are available for download at www.twinco.club

GMA-340 Audio Panel/Intercom

SL-30 Nav-COM-Glideslope

SkyBeacon ADS-B

- -Be sure to complete flight logbook and arrange for fueling (845-849-3770)
- -Note squawks in flight logbook and report on Schedulemaster system.

Last Updated: 9/17/19